

September, 2017

CLEAN

SAFE

HEALTHY

SCHOOLS

Amity Regional School
District No. 5

25 Newton Road

Woodbridge, CT 06525

Phone: 203-397-4817

Fax: 203-397-4864



Amity Regional School District No. 5

Facilities Department Monthly Report

Completed Projects:

- The ice machine at the stadium field house quit working. Our in-house personnel ordered the parts and completed the repair.
- The ice machine in the culinary classroom at Amity Regional High School quit working. Our in-house personnel ordered the parts and completed the repair.
- The HVAC upgrade project at Amity Middle School, Bethany Campus, has been completed.
- The parking lot replacement project at Amity Regional High School was completed.
- The air handler replacement project at Amity Regional High School was completed.
- The dugouts on the baseball field at Amity Regional High School were repainted.
- The sign posts in front of Amity Middle School, Bethany Campus, were repainted.
- The chiller at Amity Middle School, Orange Campus, developed a problem with one of the sections. Replacement parts were ordered and installed by Trane.
- Appropriately sized toilets were ordered and installed in the new Special Education room at Amity Regional High School.
- Numerous start-of-school projects, such as hanging bulletin boards and assembling furniture, were completed at all three schools.

Projects in process:

- Two remaining bond referendum projects are actively being worked on. The tennis courts are done. The new windscreen for the courts has been ordered. The culinary classroom renovation is in progress.
- De-stratification fans were ordered for the Student Street corridor at Amity Regional High School. The fans were installed by in-house personnel and are operational. We have our controls contractor scheduled to program the control sequence.
- Preventive Maintenance on the snow removal equipment has been started so we are ready for the winter season.
- The heat exchanger at Amity Regional High School was damaged during an overheating event. It is currently being rebuilt and safeguards are being installed to prevent a future occurrence.

Outstanding issues to be addressed:

- None at this time.